STAR ONLINE PUBLICATION

Case Number: S2408000042

Release Date: April 2024

Symptom/Vehicle Issue: ACC (Accessory Position) Etching on Start/Stop Button Missing

Discussion: The ACC (Accessory Position) etching on the Start/Stop Button may be missing because the incorrect Keyless Ignition Node (KIN) was installed.

NOTE: For this STAR Online to apply there should be no issue with the ignition switch or the switching of positions, only the indication of the ACC lamp around the switch when in the ACC position. There is also cluster EVIC indication when the ignition is in the ACC position.

Diagnosis: Inspect the Start/Stop button for missing ACC etching in the location of the red arrow shown in Fig. 1.



Fig. 1
Stop/Start Button

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

Repair: If the ACC etching is missing, replace the KIN using the standard replacement part number which at time of publication is 68336255AC. Always verify you have the most current part number by using the vehicles VIN in STAR parts.

Refer to the detailed service procedures listed in DealerCONNECT>Service Library under: 08 - Electrical / 8E - Electronic Control Modules / Module, Keyless Ignition Node (KIN) /Removal and Installation.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found