STELLANTIS
PARTS & SERVICES

Technical Service Bulletin (TSB)

Uconnect® Screen Image Changes Size, Moves Or Is Out Of Place Unprompted

REFERENCE:	**TSB:** 08-270-26 **GROUP:** 08 - Electrical	**Date:**	July 10, 2026	**REVISION:**	—
VEHICLES AFFECTED:	**2022 - 2024 (DT) RAM 1500 Pickup** **This bulletin applies to vehicles equipped with a Uconnect 5 Nav W 12.0" Display (Sales Codes UBQ and UEQ).**			**MARKET APPLICABILITY:** ☒ NA ☐ MEA ☐ SA ☐ IAP ☐ EE ☐ CH **NOTE: This bulletin applies to the North America markets.**	
CUSTOMER SYMPTOM:	**Customers may experience the following:** • The Uconnect® screen image changes size, moves or is out of place unprompted.				
CAUSE:	**Under investigation**				

DISCUSSION:

This Information Only bulletin contains information regarding when customers experience the Uconnect® screen image unexpectedly changes size, moves or is out of place. This symptom is currently under investigation. **Do not replace the radio for this symptom.**

POLICY:

Information Only