SAFETY RECALL

INTERNATIONAL

Second-Row Seat Belt Buckle Anchor

Reference: 67D

FCA US LLC

Remedy available for

2019-2026 (DT) Ram 1500 Pickup

Template Version 1.8

Revision	Edition	Detail
1	August 2026	Parts Information updated.

SYMPTOM DESCRIPTION

The second-row center and/or second-row driver side seat belt buckle anchor on about 74,084 of the above vehicles may not have been properly attached to the body structure during vehicle assembly, which may result in reduced occupant restraint capabilities. Reduced load management by the seat belt buckle may result in injury to vehicle occupants in certain types of driving conditions or crashes.

The condition above fails to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) 571.210 S4.2.4 requires that, "Anchorages, attachment hardware, and attachment bolts shall be tested by simultaneously loading them in accordance with the applicable procedures "[...]". A seat belt buckle anchor not properly fastened may reduce load management capability and occupant restraint effectiveness.

SCOPE

NOTE: Some vehicles above may have been identified as not involved in this recall and therefore have been excluded from this recall.

IMPORTANT: Some of the involved vehicles may be in dealer new vehicle inventory. Dealers should complete this recall service on these vehicles before retail delivery. Dealers should also perform this repair on vehicles in used vehicle inventory and those vehicles in for service. Involved vehicles can be determined by using the VIP inquiry process.

REPAIR TO BE PERFORMED

Inspect and, if necessary, attach the second-row seat belt buckle anchor to the body structure.

COMPLETION REPORTING / REIMBURSEMENT

Claims paid will be used by FCA US LLC to record recall service completions and provide dealer payments.

Use the following labor operation numbers and time allowances:

Labor Description	Number	Hrs
Inspect the Second-Row Center and/or Driver Side Seat Belt Buckle Anchor is Properly Secured	23-67-D1-81	0.2
Inspect/Replace the Seat Belt Buckle Anchor Bolt and Tighten to the Proper Torque Specification	23-67-D1-82	0.2

Add the cost of the recall parts plus applicable dealer allowance to your claim.

NOTE: See the FCA International Warranty Policy and Procedure Manual, Claim Entry Section – Recall Claims for claim processing instructions.

PARTS INFORMATION

NOTE: No parts are required to perform the inspection portion of this service procedure. Less than 1% of vehicles are suspected to require bolt replacement.

Part No.	MSQ.	Part Name
CSZT03D5AA	5	Bolt and Washer, Hex Head, M12X1.75X43.00

NPN is used for Mopar bulk parts that may service more than one vehicle.

PARTS RETURN

No parts return required for this campaign.

Strictly respect STELLANTIS Group safety, cleanliness, and environmental instructions for any vehicle service.
Document exclusively reserved for dealer information. Internal distribution to be ensured by dealer.
Reproduction forbidden without the written agreement of STELLANTIS Group. (C) 2026 STELLANTIS Group. All Rights Reserved (tdb)

SPECIAL TOOLS

No Special Tools are required to perform this service procedure.

OWNER NOTIFICATION / SERVICE SCHEDULING

All involved vehicle owners should be notified of the service requirement by their Dealer. Owners are requested to schedule appointments for this service.

VEHICLE LISTS, GLOBAL RECALL SYSTEM, VIP AND DEALER FOLLOW UP

All involved vehicles have been entered into the Global Recall System (GRS) and Vehicle Information Plus (VIP) for Dealer inquiry as needed.

GRS provides involved Dealers with an updated VIN list of their incomplete vehicles. Completed vehicles are removed from GRS within several days of repair claim submission.

Dealers must perform this repair on all unsold vehicles before retail delivery. Dealers should also use the VIN list to follow up with all owners to schedule appointments for this repair

Strictly respect STELLANTIS Group safety, cleanliness, and environmental instructions for any vehicle service.
Document exclusively reserved for dealer information. Internal distribution to be ensured by dealer.
Reproduction forbidden without the written agreement of STELLANTIS Group. (C) 2026 STELLANTIS Group. All Rights Reserved (tdb)

SERVICE PROCEDURE

Second Row: Center and/or Left-Side Seat Belt Buckle Anchor

1. Fold the second-row seat cushions up to access the center and left-side seat belt buckle anchor bolts (Figure 1).
2. Visually inspect to confirm both seatbelt buckle anchors are secured to the vehicle with the bolt. If not, replace the bolt and tighten to 55 N·m (41 Ft. Lbs.) (Figure 1).
3. Grasp the seatbelt buckle anchors and try to move or swivel them around the bolt. If movement is possible, replace the bolt and tighten to 55 N·m (41 Ft. Lbs.) (Figure 1).
4. If the seatbelt buckle anchor passed the first two inspection steps or was repaired during one of the prior steps, the vehicle may be returned to the customer or inventory.



Figure 1 – Second Row: Center and Left-Side Seat Belt Buckle Anchors

Strictly respect STELLANTIS Group safety, cleanliness, and environmental instructions for any vehicle service.
Document exclusively reserved for dealer information. Internal distribution to be ensured by dealer.
Reproduction forbidden without the written agreement of STELLANTIS Group. (C) 2026 STELLANTIS Group. All Rights Reserved (tdb)

LOGO

VEHICLE PICTURE

PRODUCT SAFETY RECALL

67D – Rear Seat Buckle Assembly

Dear RAM customer, it is extremely important to take steps now to repair your vehicle to ensure the safety of you and your passengers.

FCA US LLC has decided that certain [2019-2026 model year (DT) Ram 1500 Pickup] vehicles fail to comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 571.210 Seat belt assembly anchorages.

This notice applies to your vehicle:
[Model Year and Model]
VIN xxxxxxxxxxxxxxxxx
(license plate as optional)

Your VIN number is on the vehicle label and/or on the vehicle registration certificate.

CONSUMER OPTIONS TO GET MORE INFORMATION:

1) Call your Jeep authorized Repairer

2) Call the Recall Support free phone (EE G10* while for Importers they will replace with their ones) (available in the relevant official languages) of the EU Union.

3) Visit the RAM App or Website (ref. for example Customer CHECK VIN).

Alert to the Consumer: If you know other persons with the same vehicle model please ask them to check their VINs on the RAM App or Website.

For G10* (France, Italy, Spain, Portugal, Germany, UK, Netherlands, Belgium, Poland and Austria) = 0080008251001

DESCRIPTION OF THE ISSUE

The second-row center and/or second-row driver side seat belt buckle anchor on your vehicle may not have been properly attached to the body structure during vehicle assembly, which may result in reduced occupant restraint capabilities. **Reduced occupant restraint capabilities can increase the risk of injury to vehicle occupants in certain types of driving conditions or crashes.**

The condition above fails to comply with the requirements of FMVSS No. 571.210 S4.2.4 requires that, "Anchorages, attachment hardware, and attachment bolts shall be tested by simultaneously loading them in accordance with the applicable procedures "[...]". A seat belt buckle anchor not properly fastened may reduce load management capability and occupant restraint effectiveness.

DEALER ACTION

FCA US LLC will repair your vehicle free of charge (parts and labor). To do this, your dealer will inspect and, if necessary, attach the second-row seat belt buckle anchor to the body structure. The estimated repair time is 30 minutes. In addition, your dealer will require your vehicle for proper check-in, preparation, and check-out during your visit, which may require more time.

CONSUMER ACTION

Your time is important to us, so we recommend that you schedule a service appointment to minimize your inconvenience. Please bring this letter with you to your dealership.

Thank you for your understanding and we regret the inconvenience.
We look forward to seeing you.
Yours sincerely.

If you no longer own this vehicle, we would be grateful if you would kindly forward this letter to the current owner, or complete the section below and return it to :
Export : “Name and address of Point of Sale and/or postal service provider”.
1- Clot-1: “67D” “VIN” “CODE_PDV » « LIB_PDV »
VEHICLE ALREADY CHECKED BY .....
I no longer own the above vehicle, it has been: SOLD ☐ STOLEN ☐ SCRAPPED ☐
I transferred ownership of the vehicle to: Mr ☐ Mrs ☐ Ms ☐ Company ☐
Surname: ..... First name: .....
Address: .....
Post Code: ..... Town: ..... Country: .....