STELLANTIS
PARTS & SERVICES

Technical Service Bulletin (TSB)

Instrument Panel Cluster (IPC) Flicker Turn By Turn

REFERENCE:	**TSB:** 08-207-26 **GROUP:** 08 - Electrical	**Date:**	May 6, 2026	**REVISION:**	—

VEHICLES AFFECTED:	**2022 - 2026 (D2) RAM 3500 Pickup** **2022 - 2026 (DD) RAM 3500 Cab Chassis** **2022 - 2023 (DF) RAM 3500 10K LB.Cab Chassis** **2024 - 2026 (DJ) RAM 2500 Pickup** **2022 - 2026 (DP) RAM 4500/5500 Cab Chassis** **2022 - 2026 (DT) RAM 1500 Pickup** **2026 (EJ) Jeep Recon** **2024 - 2026 (JL) Jeep Wrangler** **2025 - 2026 (KM) Jeep Cherokee / Wagoneer S** **2024 - 2026 (LB) Dodge Charger** **2022 - 2026 (MP) Jeep Compass** **2021 - 2027 (RU) Chrysler Pacifica / Voyager** **2022 - 2026 (VF) RAM Promaster** **2022 - 2026 (WD) Dodge Durango** **2023 - 2026 (WL) Jeep Grand Cherokee / Grand Cherokee L** **2022 - 2026 (WS) Wagoneer / Grand Wagoneer** **This bulletin applies to vehicles equipped with one of the following radios:** • Uconnect 5 Nav W 8.4" Display (Sales Code UBL, UEL, or UFL) • Uconnect 5 W 10.1" Display (Sales Code UBG or UEG) • Uconnect 5 Nav W 10.1" Display (Sales Code UBN, UEN, or UFN) • Uconnect 5 Nav W 12.0" Display (Sales Code UBQ, UEQ, or UFQ) • Uconnect 5 W/ 12.3" Display (Sales Code UBP, UEP, or UFP) • Uconnect 5 Nav W 12.3" Display (Sales Code UBX, UEX, or UFX) • Uconnect 5 Nav W 14.4" Display (Sales Code UBW, UEW, or UFW)	**MARKET APPLICABILITY:** ☒ NA ☐ MEA ☐ SA ☐ IAP ☐ EE ☐ CH **NOTE: This bulletin applies to the North America market.**
CUSTOMER SYMPTOM:	**The customer may experience flickering on their Instrument Panel Cluster (IPC) when the turn-by-turn feature is enabled. This issue occurs when using Google Maps for Navigation via CarPlay.**	
CAUSE:	**IPC Flickering**	

DISCUSSION:

This Information Only bulletin contains information helpful or useful for technicians understanding this only occurs with Carplay while using Google Maps for navigation and most likely to occur after updating PHONE to IOS 26.4.x (any version). A future IOS update version will bring improvement and currently has an eta of 2nd quarter 2026. Parts should not be replaced for this issue.

POLICY:

Information Only.