STAR ONLINE PUBLICATION

Case Number: S2623000057

Release Date: October 2026

Symptom/Vehicle Issue: After Recent Service, A Replacement Occupant Classification Module (OCM) Is Non-Responsive.

Models Affected: 2019-2024 Ram 1500 (DT)

Customer Complaint/Technician Observation: Technician finds a replacement OCM seat foam assembly is non-responsive on wiTECH. Air Bag warning light illuminated. One or more of the following diagnostic trouble code(s) (DTCs) may be set:

U0154-00-LOST COMMUNICATION WITH OCCUPANT CLASSIFICATION MODULE
B00A0-81-OCCUPANT CLASSIFICATION SYSTEM-INVALID SERIAL DATA RECEIVED
B223D-00-OCM DTC PRESENT
U0452-64-IMPLAUSIBLE DATA RECEIVED FROM RESTRAINTS CONTROL MODULE-SIGNAL PLAUSIBILITY FAILURE

Discussion: Engineering is investigating complaints. It is not recommended to replace the OCM again as it will most likely not repair the condition. It is not recommended to release a vehicle with an Air Bag light on and/or DTCs set for the restraint system. There will be a future service update. Use the “get notified” click button for this document.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous case details that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.