STELLANTIS
PARTS & SERVICES

Technical Service Bulletin (TSB)

ACC Etching on Start/Stop Button Shy

REFERENCE:	**TSB:** 08-126-24 **GROUP:** 08 - Electrical	**Date:**	May 14, 2024	**REVISION:**	08-184-23
VEHICLES AFFECTED:	**2023 (DT) RAM 1500 Pickup** **This bulletin applies to vehicles built on May 09, 2023 (MDH 0509XX) equipped with Remote Keyless Entry (Sales Code GXM).**			**MARKET APPLICABILITY:** ☒ NA ☐ MEA ☐ SA ☐ IAP ☐ EE ☐ CH	
CUSTOMER SYMPTOM:	**Customers may experience:** • ACC (Accessory Position) etching missing on Stop/Start button.				
CAUSE:	**Incorrect Stop/Start button installed.**				

This bulletin supersedes Technical Service Bulletin (TSB) 08-184-23, date of issue July 27, 2023, which should be removed from your files. All revisions are highlighted with **asterisks and include an updated RSU statement and adding a RSU cancellation note.**

****This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 23-223, date of issue July 27, 2023. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.****

NOTE: **This proactive service action no longer in effect. Please follow published service procedures in Service Library to diagnose and repair the vehicle.**

POLICY:

Information Only.