STELLANTIS
PARTS & SERVICES

Technical Service Bulletin (TSB)

Cold Engine Ticking Noise

REFERENCE:	**TSB:** 09-001-24 REV. C **GROUP:** 09 - Engine	**Date:**	July 13, 2024	**REVISION:**	09-001-24 REV. B
VEHICLES AFFECTED:	**2019 - 2024 (DT) Ram 1500 Pickup** **This bulletin applies to vehicles equipped with a 5.7L V8 Hemi MDS VVT E-torque Engine (Sales Code EZL) or a 5.7L V8 Hemi MDS VVT Engine (Sales Code EZH).**			**MARKET APPLICABILITY:** ☒ NA ☒ MEA ☒ SA ☒ IAP ☒ EE ☐ CH	
CUSTOMER SYMPTOM:	**The customer may describe a ticking noise from the exhaust manifold location(s) when cold.**				
CAUSE:	**Exhaust manifold**				

This bulletin supersedes Technical Service Bulletin (TSB) 09-001-24 REV. B, date of issue March 23, 2024 , which should be removed from your files. All revisions are highlighted with **asterisks and include a cancellation note.**

NOTE: **This TSB is no longer needed, follow published service information for diagnostics and repairs.**

POLICY:

Information Only

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.