EQUIPMENT SAFETY RECALL – NORTH AMERICA

High Pressure Fuel Pump - Equipment

Reference: 02A

FCA Canada Inc.

Parts Recalled

Mopar High Pressure Fuel Pump 68501449AA
Mopar 3.0L Diesel Engine 05162119BB
Mopar 3.0L Diesel Engine 05162111CB
Mopar 3.0L Diesel Engine 05158048AH
Mopar 3.0L Diesel Engine 05158052AG

Intended for use on some 2022-2023 DT Ram 1500 Pickup and 2021-2023 JL Wrangler and JT Gladiator vehicles.

Template Version 1.8

Revision	Edition	Detail
0	November 2023	Initial Version.

SYMPTOM DESCRIPTION

Some of the High Pressure Fuel Pumps (HPFPs) listed above could fail prematurely. A high-pressure fuel pump failure may introduce internally failed component debris into the fuel system potentially causing fuel starvation if installed into a vehicle. Vehicle occupants may notice a Malfunction Indicator Lamp, service Electronic Throttle Control indicator, a fuel leak at the HPFP, or excessive noise from the HPFP. **Fuel starvation may result in an unexpected loss of motive power, which can cause a vehicle crash without prior warning.**

REPAIR TO BE PERFORMED

Inspect the pump part number:

Part number
Mopar High Pressure Fuel Pump 68501449AA
Mopar 3.0L Diesel Engine 05162119BB
Mopar 3.0L Diesel Engine 05162111CB
Mopar 3.0L Diesel Engine 05158048AH
Mopar 3.0L Diesel Engine 05158052AG

Pump or engine suspect, repurchase the pump or engine.

Dealer should add part (reimbursement) to claim when using LOP.

If the recalled HPFP or remanufactured engine assembly with part number listed above has been installed into a vehicle, the repair will be covered under recall 01A.

COMPLETION REPORTING / REIMBURSEMENT

Claims for vehicles that have been serviced must be submitted on the DealerCONNECT Claim Entry Screen located on the Service tab. Claims paid will be used by FCA to record recall service completions and provide dealer payments.

Use the following labour operation numbers and time allowances:

Labour Description	Number	Hrs
Inspect High Pressure Fuel Pump Part Number	14-02-A1-81	0.0
$5.00 Handling Fee for Equipment Safety Recall 02A part exchange	95-14-02-50	$5.00

NOTE: See the Warranty Administration Manual, Recall Claim Processing Section, for complete recall claim processing instructions.

PARTS RETURN

No parts return required for this campaign.

Render the recalled part unusable and discard.

SPECIAL TOOLS

No special tools required for this campaign.

Strictly respect STELLANTIS Group safety, cleanliness, and environmental instructions for any vehicle service.
Document exclusively reserved for dealer information. Internal distribution to be ensured by dealer.
Reproduction forbidden without the written agreement of STELLANTIS Group. (C) 2023 STELLANTIS Group. All Rights Reserved

DEALER NOTIFICATION

To view this notification on DealerCONNECT, select "Global Recall System" on the Service tab, then click on the description of this notification.

OWNER NOTIFICATION / SERVICE SCHEDULING

All involved vehicle owners known to FCA are being notified of the service requirement by first class mail. They are requested to schedule appointments for this service with their dealers. A generic copy of the owner letter is attached.

ADDITIONAL INFORMATION

If you have any questions or need assistance in completing this action, please contact your Service and Parts District Manager.

FCA Canada Inc.

Strictly respect STELLANTIS Group safety, cleanliness, and environmental instructions for any vehicle service.
Document exclusively reserved for dealer information. Internal distribution to be ensured by dealer.
Reproduction forbidden without the written agreement of STELLANTIS Group. (C) 2023 STELLANTIS Group. All Rights Reserved

CAMPAIGN NOTIFICATION
An important improvement for your vehicle is available.
NOTIFICATION DE CAMPAGNE
Une amélioration importante pour.

SCAN TO VIEW RECALLS

FCA
FIAT CHRYSLER AUTOMOBILES

EQUIPMENT CAMPAIGN 02A
HIGH PRESSURE FUEL PUMP

Dear Vehicle Owner:

FCA CANADA INC., (FCA) HAS ANNOUNCED AN EQUIPMENT CAMPAIGN, WHICH RELATES TO MOTOR VEHICLE SAFETY, EXISTS IN CERTAIN MOPAR 3.0L DIESEL ENGINES AND IN CERTAIN HIGH PRESSURE FUEL PUMPS INTENDED FOR USE ON SOME 2022-2023 DT RAM 1500 PICKUP AND 2021-2023 JL WRANGLER AND JT GLADIATOR VEHICLES.

Mopar High Pressure Fuel Pump 68501449AA
Mopar 3.0L Diesel Engine 05162119BB
Mopar 3.0L Diesel Engine 05162111CB
Mopar 3.0L Diesel Engine 05158048AH
Mopar 3.0L Diesel Engine 05158052AG

Your vehicle must be repaired because:
FCA records indicate that you may have purchased a MOPAR high pressure fuel pump (HPFP) or engine assembly with an installed HPFP for your vehicle. Some HPFPs could fail prematurely. A high-pressure fuel pump failure may introduce internally failed component debris into the fuel system potentially causing fuel starvation if installed into a vehicle. Vehicle occupants may notice a Malfunction Indicator Lamp, service Electronic Throttle Control indicator, a fuel leak at the HPFP, or excessive noise from the HPFP. Fuel starvation may result in an unexpected loss of motive power, which can cause a vehicle crash without prior warning.

If you purchased an HPFP, or a remanufactured engine with an HPFP on it and have not yet installed it, FCA will reimburse your purchase with the return of the HPFP or remanufactured engine assembly.

If the recalled HPFP or remanufactured engine assembly with part number listed above has been installed into a vehicle, the repair will be covered under recall 01A.

We apologize for any inconvenience and thank you for your attention to this very important matter.

FCA Canada Inc.
National Service and Parts Manager

What You Must Do:

Contact an authorized FCA Canada dealer to schedule a service appointment.

What Your Dealer Will Do:

Please bring your HPFP or remanufactured engine assembly, and this letter with you to your dealership.

FREQUENTLY ASKED QUESTIONS

WHERE CAN I FIND MORE INFORMATION ON THIS RECALL OR ANY OTHER RECALL AFFECTING MY VEHICLE?

By Web:	recalls.mopar.ca
By Phone:	(800) 465-2001
By Email:	www.fcacanada.ca/en/contact_us.php
By Mail:	FCA Canada Customer Care Centre P.O. Box 1621, Windsor, ON N9A 4H6

WHAT IF I ALREADY PAID TO HAVE THIS REPAIR COMPLETED?
If you have already experienced this specific condition and have paid to have it repaired, you will still be required to have the campaign performed by an authorized FCA Canada dealer at no charge to you. Once completed, please send your original receipts and/or adequate proof of payment along with the campaign invoice to the following address for **further review of possible reimbursement**: FCA Canada Customer Care Centre, P.O. Box 1621, Windsor, ON N9A 4H6.

HOW DO I UPDATE MY NAME AND ADDRESS OR IF I NO LONGER OWN THIS VEHICLE?
Contact the Customer Name & Address Call Centre at 1-800-373-1474 to update your information.

FCA IS THE MANUFACTURER OF THE FOLLOWING

ALFA ROMEO · CHRYSLER · DODGE · FIAT · Jeep · RAM · MOPAR