INTERNATIONAL

FIAT CHRYSLER AUTOMOBILES

04/14/2023

New Safety Recall Advanced Communication – 02A

FCA US LLC has announced an equipment safety recall on certain:

Mopar High Pressure Fuel Pump 68501449AA
Mopar 3.0L Diesel Engine 05162119BB
Mopar 3.0L Diesel Engine 05162111CB
Mopar 3.0L Diesel Engine 05158048AH
Mopar 3.0L Diesel Engine 05158052AG

REASON FOR THIS SAFETY RECALL

Some of the above 3.0L diesel engines and replacement High Pressure Fuel Pumps ("HPFPs") may wear prematurely and could fail internally. A high pressure fuel pump failure may introduce internally failed component debris into the fuel system potentially causing fuel starvation if installed into a vehicle. Fuel starvation may result in an unexpected loss of motive power, which can cause vehicle crash without prior warning.

SERVICE ACTION

FCA US will conduct a voluntary safety recall on all affected parts to repurchase suspect HPFPs and uninstalled engines. For installed engines, FCA US will replace the HPFP, and inspect and, if necessary, replace additional fuel system components. The remedy for this condition is not currently available. Dealers will be notified of the launch of this safety recall by way of established communication methods. This recall is estimated to launch in 3rd Quarter of 2023.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries regarding involved vehicles.

Customer Services Field Operations
FCA US LLC