EQUIPMENT SAFETY RECALL

NORTH AMERICA

ABS Module Configuration Mismatch

Reference: 76B / NHTSA 24E-075

FCA US LLC

Parts Recalled

MOPAR Antilock Brake System (ABS) Modules 68531864AD, 68531864AG, 68531864AH, 68436462AB, 68436462AC, 68436462AD, 68436462AF, 68436462AG, 68436462AJ, 68436462AK, 68436462AL, 68436461AB, 68436461AC, 68436461AD, 68436461AE, 68436461AF, 68436461AI, 68436461AJ, 68436461AK, 68415321AE, 68415321AF, 68415321AG, 68415321AH, 68415318AE, 68415318AF and 68415318AG intended for use on 2021 - 2024 (DT) Ram 1500 Pickups with Sales Code TRX, NHZ (Adaptive Cruise Control) or NHM (without Adaptive Cruise Control).

Mopar ABS Modules 68436462AB, 68436462AC, 68436462AD, 68436462AF, 68436462AG, 68436462AJ, 68436462AK, 68436462AL, 68436461AB, 68436461AC, 68436461AD, 68436461AE, 68436461AF, 68436461AI, 68436461AJ and 68436461AK intended for use on 2019 (DT) Ram 1500 Pickups built on or after 6/6/2018.

Mopar ABS Modules 68415321AE, 68415321AF, 68415321AG, 68415321AH, 68415318AE, 68415318AF and 68415318AG intended for use on 2019 (DT) Ram 1500 Pickups built up to 6/6/2018.

Template Version 1.8

Revision	Edition	Detail
0	September 2024	Initial Version.

SYMPTOM DESCRIPTION

The Anti-Lock Braking System (ABS) module is setting a malfunction indicator lamp (MIL), disabling the Electronic Stability Control System (ESC), which may result in a compromised vehicle safety system. Failure of the ESC system when intervention is expected and/or relied upon can cause a vehicle crash without prior warning.

The condition described above does not comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 571.126 S5.1.2 ESC Functionality requires that the ESC system "Is operational during all phases of driving including acceleration, coasting, and deceleration (including braking) [...]." The suspect ABS control modules, when installed in a vehicle may cause the ESC system to be disabled when certain conditions are met.

REPAIR TO BE PERFORMED

This recall is applicable only to the Mopar ABS modules listed above**.**

If the recalled ABS Module part number listed above has been installed into a vehicle, the vehicle will be covered under recall 75B. Please complete the repair according to the 75B dealer instructions and claim the appropriate 75B LOPs.

If the recalled ABS Module part number listed above has not been installed into a vehicle, complete the ABS Module repurchase according to these instructions and claim the appropriate 76B LOPs.

Strictly respect STELLANTIS Group safety, cleanliness, and environmental instructions for any vehicle service.
Document exclusively reserved for dealer information. Internal distribution to be ensured by dealer.
Reproduction forbidden without the written agreement of STELLANTIS Group. (C) 2024 STELLANTIS Group. All Rights Reserved (djt)

EQUIPMENT SAFETY RECALL

NORTH AMERICA

ABS Module Configuration Mismatch

Reference: 76B / NHTSA 24E-075

FCA US LLC

COMPLETION REPORTING / REIMBURSEMENT

Claims for vehicles that have been serviced must be submitted on the DealerCONNECT Claim Entry Screen located on the Service tab. Claims paid will be used by FCA to record recall service completions and provide dealer payments.

Use the following labor operation numbers and time allowances:

For Over-The-Counter parts return/repurchase, claim the below LOPs.

Labor Description	Number	Hrs
Module, Antilock Brake System (ABS) - Repurchase	08-76-B1-80	0.0

Related Labor Description	Number	US Currency
Dealership Handling Fee for Module Repurchase	95081954	$5.00

NOTE: See the Warranty Administration Manual, Recall Claim Processing Section, for complete recall claim processing instructions.

PARTS INFORMATION

No parts are required to perform this service procedure.

PARTS RETURN

No parts return required for this campaign.

DEALER NOTIFICATION

To view this notification on DealerCONNECT, select “Global Recall System” on the Service tab, then click on the description of this notification.

OWNER NOTIFICATION / SERVICE SCHEDULING

All involved vehicle owners known to FCA are being notified of the service requirement by first class mail. They are requested to schedule appointments for this service with their dealers.

ADDITIONAL INFORMATION

If you have any questions or need assistance in completing this action, please contact your Service and Parts District Manager.

Customer Services / Field Operations
FCA US LLC.

Strictly respect STELLANTIS Group safety, cleanliness, and environmental instructions for any vehicle service.
Document exclusively reserved for dealer information. Internal distribution to be ensured by dealer.
Reproduction forbidden without the written agreement of STELLANTIS Group. (C) 2024 STELLANTIS Group. All Rights Reserved (djt)