EQUIPMENT SAFETY RECALL

NORTH AMERICA

ABS Configuration Mismatch

Reference: 76B

FCA Canada Inc.

Parts Recalled

MOPAR Antilock Brake System (“ABS”) Modules 68531864AD, 68531864AG, 68531864AH, 68436462AB, 68436462AC, 68436462AD, 68436462AF, 68436462AG, 68436462AJ, 68436462AK, 68436462AL, 68436461AB, 68436461AC, 68436461AD, 68436461AE, 68436461AF, 68436461AI, 68436461AJ, 68436461AK, 68415321AE, 68415321AF, 68415321AG, 68415321AH, 68415318AE, 68415318AF and 68415318AG intended for use on 2021 - 2024 (DT) Ram 1500 Pickups with Sales Code TRX, NHZ (Adaptive Cruise Control) or NHM (without Adaptive Cruise Control).

Mopar ABS Modules 68436462AB, 68436462AC, 68436462AD, 68436462AF, 68436462AG, 68436462AJ, 68436462AK, 68436462AL, 68436461AB, 68436461AC, 68436461AD, 68436461AE, 68436461AF, 68436461AI, 68436461AJ and 68436461AK intended for use on 2019 (DT) Ram 1500 Pickups built on or after 6/6/2018.

Mopar ABS Modules 68415321AE, 68415321AF, 68415321AG, 68415321AH, 68415318AE, 68415318AF and 68415318AG intended for use on 2019 (DT) Ram 1500 Pickups built up to 6/6/2018.

Template Version 1.8

Revision	Edition	Detail
0	October 2024	Initial Version.

SYMPTOM DESCRIPTION

The Anti-Lock Braking System (“ABS”) module is setting a malfunction indicator lamp (“MIL”), disabling the Electronic Stability Control System (“ESC”), which may result in a compromised vehicle safety system. Failure of the ESC system when intervention is expected and/or relied upon can cause a vehicle crash without prior warning.

The condition described above does not conform to the requirements of Canada Motor Vehicle Safety Standard (“CMVSS”) 126 Electronic Stability Control Systems for Light Vehicles. The suspect ABS control modules, when installed in a vehicle may cause the ESC system to be disabled when certain conditions are met.

REPAIR TO BE PERFORMED

This recall is applicable only to the Mopar ABS modules listed above**.**

If the recalled ABS Module part number listed above has been installed into a vehicle, the vehicle will be covered under 75B. Please complete the repair according to the 75B dealer instructions and claim the appropriate 75B LOPs.

If the recalled ABS Module part number listed above has not been installed into a vehicle, complete the ABS Module repurchase according to the 76B instructions and claim the appropriate 76B LOPs.

COMPLETION REPORTING / REIMBURSEMENT

Claims for vehicles that have been serviced must be submitted on the DealerCONNECT Claim Entry Screen located on the Service tab. Claims paid will be used by FCA to record recall service completions and provide dealer payments.

Use the following labour operation numbers and time allowances:

For Over-The-Counter parts return/repurchase, claim the below LOPs.

Labour Description	Number	Hrs
Module, Antilock Brake System (“ABS”) - Repurchase	08-76-B1-80	0.0

Related Labor Description	Number	
Dealership Handling Fee for Module Repurchase	95081952	$5.00

NOTE: See the Warranty Administration Manual, Recall Claim Processing Section, for complete recall claim processing instructions.

Strictly respect STELLANTIS Group safety, cleanliness, and environmental instructions for any vehicle service.
Document exclusively reserved for dealer information. Internal distribution to be ensured by dealer.
Reproduction forbidden without the written agreement of STELLANTIS Group. (C) 2024 STELLANTIS Group. All Rights Reserved

EQUIPMENT SAFETY RECALL

NORTH AMERICA

ABS Configuration Mismatch

Reference: 76B

FCA Canada Inc.

PARTS INFORMATION

No parts are required to perform this service procedure.

PARTS RETURN

No parts return required for this campaign.

DEALER NOTIFICATION

To view this notification on DealerCONNECT, select “Global Recall System” on the Service tab, then click on the description of this notification.

OWNER NOTIFICATION / SERVICE SCHEDULING

All involved vehicle owners known to FCA are being notified of the service requirement by first class mail. They are requested to schedule appointments for this service with their dealers. A generic copy of the owner letter is attached.

ADDITIONAL INFORMATION

If you have any questions or need assistance in completing this action, please contact your Service and Parts District Manager.

FCA Canada Inc.

Strictly respect STELLANTIS Group safety, cleanliness, and environmental instructions for any vehicle service.
Document exclusively reserved for dealer information. Internal distribution to be ensured by dealer.
Reproduction forbidden without the written agreement of STELLANTIS Group. (C) 2024 STELLANTIS Group. All Rights Reserved

CAMPAIGN NOTIFICATION
An important improvement for your vehicle is available.
NOTIFICATION DE CAMPAGNE
Une amélioration importante pour.

SCAN TO VIEW RECALLS

FCA
FIAT CHRYSLER AUTOMOBILES

EQUIPMENT CAMPAIGN 76B
ANTILOCK BRAKE SYSTEM MODULE CONFIGURATION MISMATCH

Dear Vehicle Owner:

FCA Canada Inc. has decided that a defect, which relates to motor vehicle safety, exists in certain MOPAR Antilock Brake System ("ABS") Modules intended for use on 2019 and 2021 through 2024 Ram 1500 Pickups:

68415318AG, 68415321AH, 68436461AK, 68436462AL, 68531864AH, 68415318AE, 68415318AF, 68415321AE, 68415321AF, 68415321AG, 68436461AB, 68436461AC, 68436461AD, 68436461AE, 68436461AF, 68436461AI, 68436461AJ, 68436462AB, 68436462AC, 68436462AD, 68436462AF, 68436462AG, 68436462AJ, 68436462AK, 68531864AD, 68531864AG

Your vehicle must be repaired because:
FCA Canada records indicate that you may have purchased an ABS module for your vehicle. Some ABS modules are setting a malfunction indicator lamp ("MIL"), disabling the Electronic Stability Control System ("ESC"), which may result in a compromised vehicle safety system. Failure of the ESC system can, in certain driving conditions, cause a vehicle crash without warning.

The condition described above does not conform to the requirements of Canada Motor Vehicle Safety Standard ("CMVSS") 126 Electronic Stability Control Systems for Light Vehicles. The suspect ABS control modules, when installed in a vehicle may cause the ESC system to be disabled when certain conditions are met.

We apologize for any inconvenience and thank you for your attention to this very important matter.

FCA Canada Inc.
National Service and Parts Manager

What You Must Do To Ensure Your Safety:

Contact an FCA Canada authorized dealer to schedule a service appointment.

What Your Dealer Will Do:

FCA will repair your vehicle free of charge. To do this, your dealer will update the software on installed ABS modules. Your dealer will also repurchase or replace suspect uninstalled ABS control modules. Please bring your vehicle with ABS module installed or uninstalled ABS module and this letter with you to your dealership. However, additional time may be necessary depending on how dealer appointments are scheduled and processed.

FREQUENTLY ASKED QUESTIONS

WHERE CAN I FIND MORE INFORMATION ON THIS RECALL OR ANY OTHER RECALL AFFECTING MY VEHICLE?

By Web:	recalls.mopar.ca
By Phone:	(800) 465-2001
By Email:	www.fcacanada.ca/en/contact_us.php
By Mail:	FCA Canada Customer Care Centre P.O. Box 1621, Windsor, ON N9A 4H6

WHAT IF I ALREADY PAID TO HAVE THIS REPAIR COMPLETED?
If you have already experienced this specific condition and have paid to have it repaired, you will still be required to have the campaign performed by an authorized FCA Canada dealer at no charge to you. Once completed, please send your original receipts and/or adequate proof of payment along with the campaign invoice to the following address for **further review of possible reimbursement**: FCA Canada Customer Care Centre, P.O. Box 1621, Windsor, ON N9A 4H6.

HOW DO I UPDATE MY NAME AND ADDRESS OR IF I NO LONGER OWN THIS VEHICLE?
Contact the Customer Name & Address Call Centre at 1-800-373-1474 to update your information.

FCA IS THE MANUFACTURER OF THE FOLLOWING

ALFA ROMEO · CHRYSLER · DODGE · FIAT · Jeep · RAM · MOPAR