STELLANTIS
PARTS & SERVICES

Technical Service Bulletin (TSB)

R1H UBQ/UEQ Intermittent HVAC Page Lockup

REFERENCE:	**TSB:** 08-291-26 **GROUP:** 08 - Electrical	**Date:**	July 22, 2026	**REVISION:**	—
VEHICLES AFFECTED:	**2022 - 2024 (DT) RAM 1500 Pickup** **2022 - 2024 (DJ) RAM 2500 Pickup** **This bulletin applies to vehicles equipped with Uconnect 5 Nav w 12.0" Display (Sales Codes UBQ and UEQ)**			**MARKET APPLICABILITY:** ☒ NA ☐ MEA ☐ SA ☐ IAP ☐ EE ☐ CH **NOTE: This bulletin applies to the North America market.**	
CUSTOMER SYMPTOM:	**Customers may experience one or more of the following:** • Intermittently the HVAC page on the Display Screen Module will change temperature and blower speed and then freeze. • When on the HVAC page, the Display Screen Module may not respond to touch. **All other pages operate as intended.**				
CAUSE:	**Under investigation**				

DISCUSSION:

This Information Only bulletin provides guidance for a customer reported condition listed in the Customer Symptoms above.

Engineering is currently investigating this issue. **Radio replacement isn't recommended as it will perform the same.**

POLICY:

Information Only.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.