SAFETY RECALL
NORTH AMERICA

Second-Row Seat Belt Buckle Anchor

Reference: 67D / Transport Canada 2026-371

FCA Canada Inc.

RAM

Remedy available for

2019-2026 (DT) Ram 1500 Pickup

Template Version 1.0

Revision	Edition	Detail
1	August 2026	Parts Information updated.
0	August 2026	Initial Version.

SYMPTOM DESCRIPTION

The second-row center and/or second-row driver side seat belt buckle anchor on about 156,138 of the above vehicles may not have been properly attached to the body structure during vehicle assembly, which may result in reduced occupant restraint capabilities. Reduced load management by the seat belt buckle may result in injury to vehicle occupants in certain types of driving conditions or crashes.

The condition above fails to comply with the requirements of CMVSS 210 as seat belt buckle anchors not properly fastened may reduce load management capability and occupant restraint effectiveness.

SCOPE

NOTE: Some vehicles above may have been identified as not involved in this recall and therefore have been excluded from this recall.

Some of the involved vehicles may be in dealer new/used vehicle inventory. Dealers should complete this recall service on these vehicles before retail delivery. Dealers should also perform this recall on vehicles in for service. Involved vehicles can be determined by using the VIP inquiry process.

REPAIR TO BE PERFORMED

Inspect and, if necessary, attach the second-row seat belt buckle anchor to the body structure.

ALTERNATE TRANSPORTATION

Dealers should proactively minimize customer inconvenience while the recall repair is being performed. Reference the Service Administration Manual on DealerCONNECT for options to support the customer while their vehicle is in service.

COMPLETION REPORTING / REIMBURSEMENT

Claims for vehicles that have been serviced must be submitted on the DealerCONNECT Claim Entry Screen located on the Service tab. Claims paid will be used by FCA to record recall service completions and provide dealer payments.

Use the following labour operation numbers and time allowances:

Labour Description	Number	Hrs
Inspect the Second-Row Center and/or Driver Side Seat Belt Buckle Anchor is Properly Secured	23-67-D1-81	0.2
Inspect/Replace the Seat Belt Buckle Anchor Bolt and Tighten to the Proper Torque Specification	23-67-D1-82	0.2

Strictly respect STELLANTIS Group safety, cleanliness, and environmental instructions for any vehicle service.
Document exclusively reserved for dealer information. Internal distribution to be ensured by dealer.
Reproduction forbidden without the written agreement of STELLANTIS Group. (C) 2026 STELLANTIS Group. All Rights Reserved

Second-Row Seat Belt Buckle Anchor

Reference: 67D / Transport Canada 2026-371

FCA Canada Inc.

PARTS INFORMATION

NOTE: No parts are required to perform the inspection portion of this service procedure. Less than 1% of vehicles are suspected to require bolt replacement.

Part No.		Part Name
CSZT03D5AA	5 per kit	Bolt and Washer, Hex Head, M12X1.75X43.00

NPN is used for Mopar bulk parts that may service more than one vehicle.

PARTS RETURN

No parts return required for this campaign.

SPECIAL TOOLS

No Special Tools are required to perform this service procedure.

DEALER NOTIFICATION

To view this notification on DealerCONNECT, select "Global Recall System" on the Service tab, then click on the description of this notification.

OWNER NOTIFICATION / SERVICE SCHEDULING

All involved vehicle owners known to FCA are being notified of the service requirement by first class mail. They are requested to schedule appointments for this service with their dealers.

VEHICLE LISTS, GLOBAL RECALL SYSTEM, VIP AND DEALER FOLLOW UP

All involved vehicles have been entered into the DealerCONNECT Global Recall System ("GRS") and Vehicle Information Plus ("VIP") for dealer inquiry as needed.

GRS provides involved dealers with an updated VIN list of their incomplete vehicles. The owner's name, address and phone number are listed if known. Completed vehicles are removed from GRS within several days of repair claim submission.

To use this system, click on the "**Service**" tab and then click on "**Global Recall System**." Your dealer's VIN list for each recall displayed can be sorted by: those vehicles that were unsold at recall launch, those with a phone number, city, postal code, or VIN sequence.

Dealers must perform this repair on all unsold vehicles before retail delivery. Dealers should also use the VIN list to follow up with all owners to schedule appointments for this repair.

Recall VIN lists may contain confidential, restricted owner name and address information. Use of this information is permitted for this recall only and is strictly prohibited from all other use.

ADDITIONAL INFORMATION

If you have any questions or need assistance in completing this action, please contact your Service and Parts District Manager.

Customer Services / Field Operations
FCA Canada Inc.

Strictly respect STELLANTIS Group safety, cleanliness, and environmental instructions for any vehicle service.
Document exclusively reserved for dealer information. Internal distribution to be ensured by dealer.
Reproduction forbidden without the written agreement of STELLANTIS Group. (C) 2026 STELLANTIS Group. All Rights Reserved

SERVICE PROCEDURE

Second Row: Center and/or Left-Side Seat Belt Buckle Anchor

1. Fold the second-row seat cushions up to access the centre and left-side seat belt buckle anchor bolts.

2. Visually inspect, to confirm both seatbelt buckle anchors are secured to the vehicle with the bolt. If not, replace the bolt and tighten to 55 N·m (41 ft. lbs.) (Figure 1).

3. Grasp the seatbelt buckle anchors and try to move or swivel them around the bolt. If movement is possible, replace the bolt and tighten to 55 N·m (41 ft. lbs.) (Figure 1).

4. If the seatbelt buckle anchor passed the first two inspection steps or was repaired during one of the prior steps, the vehicle may be returned to the customer or inventory.



Figure 1 - Second row: Center and Left Side Seat Belt Buckle Anchors

Strictly respect STELLANTIS Group safety, cleanliness, and environmental instructions for any vehicle service.
Document exclusively reserved for dealer information. Internal distribution to be ensured by dealer.
Reproduction forbidden without the written agreement of STELLANTIS Group. (C) 2026 STELLANTIS Group. All Rights Reserved

SAFETY
SÉCURITÉ

URGENT VEHICLE RECALL
Your vehicle has a safety recall.
RAPPEL URGENT DU VÉHICULE
Votre véhicule a un rappel de sécurité.

SCAN TO VIEW RECALLS

FCA
FIAT CHRYSLER AUTOMOBILES

SAFETY RECALL 67D (TRANSPORT CANADA 2026-371)
SECOND-ROW SEAT BELT BUCKLE ANCHORS

Dear Vehicle Owner:

This Notice is sent to you in accordance with the requirements of the ***Motor Vehicle Safety Act***.

This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

FCA US LLC HAS DECIDED THAT CERTAIN 2019-2026 MODEL YEAR RAM 1500 PICKUP TRUCKS FAIL TO COMPLY WITH CANADA MOTOR VEHICLE SAFETY STANDARD ("CMVSS") 210 SEAT BELT ANCHORAGES.

Your vehicle must be repaired because:
The second-row center and/or second-row driver side seat belt buckle anchors on your vehicle may not have been properly attached to the body structure during vehicle assembly, which may result in reduced occupant restraint capabilities.

Reduced occupant restraint capabilities can increase the risk of injury to vehicle occupants in certain types of driving conditions or crashes.

The condition above fails to comply with the requirements of CMVSS 210 as seat belt buckle anchors not properly fastened may reduce load management capability and occupant restraint effectiveness.

We apologize for any inconvenience and thank you for your attention to this very important matter.

FCA Canada Inc.
National Service and Parts Manager

Note to lessors receiving this recall notice: Federal regulations requires that you forward this recall notice to the lessee within 10 days.

What You Must Do To Ensure Your Safety:

Contact an authorized FCA Canada dealer to schedule a service appointment.

What Your Dealer Will Do:

FCA will repair your vehicle free of charge. To do this, your dealer will inspect and, if necessary, attach the second-row seat belt buckle anchor(s) to the body structure. The estimated repair time is 30 minutes. However, additional time may be necessary depending on how dealer appointments are scheduled and processed.

FREQUENTLY ASKED QUESTIONS

WHERE CAN I FIND MORE INFORMATION ON THIS RECALL OR ANY OTHER RECALL AFFECTING MY VEHICLE?

By Web:	recalls.mopar.ca
By Phone:	(800) 465-2001
By Email:	www.fcacanada.ca/en/contact_us.php
By Mail:	FCA Canada Customer Care Centre P.O. Box 1621, Windsor, ON N9A 4H6

WHAT IF I ALREADY PAID TO HAVE THIS REPAIR COMPLETED?
If you have already experienced this specific condition and have paid to have it repaired, you will still be required to have the campaign performed by an authorized FCA Canada dealer at no charge to you. Once completed, please send your original receipts and/or adequate proof of payment along with the campaign invoice to the following address for **further review of possible reimbursement**: FCA Canada Customer Care Centre, P.O. Box 1621, Windsor, ON N9A 4H6.

HOW DO I UPDATE MY NAME AND ADDRESS OR IF I NO LONGER OWN THIS VEHICLE?
Contact the Customer Name & Address Call Centre at 1-800-373-1474 to update your information.

FCA IS THE MANUFACTURER OF THE FOLLOWING

ALFA ROMEO · CHRYSLER · DODGE · FIAT · Jeep · RAM · MOPAR